
SRK02.SLDDRW 7/18/2008 1:42 PM

REV.	DESCRIPTION	ECN	DATE	BY
Α	ITEM#1 WAS	C-4261	10/23/2006	TEG
В	ITEM #1 WAS 19040-113,ADD ITEM #5	C-4979	10/30/2007	JFF
С	ADDED NEW CHART WITH HARDWARE ONLY	C-5156	2/6/2008	DRB
D	SRK02 ITEM #5 QTY. WAS 2, -01 ITEM #4 QTY WAS 2		2/14/2008	JFF
E	SRK 02 ITM #5 QTY WAS 4,-01 ITM #4 QTYWAS 4	C5434	5/14/2008	JFF
F	ADDED EXPLODED VIEW; REMOVED OLD CHARTS WITH NEW	C-5621	7/18/2008	TLK

ITEM NO.	QTY	PART NO.	DESCRIPTION
1	4	10036	CAPSCREW 1.12X8.5UNF GR8
2	8	10045	WASHER FLAT 1.12 HARDENED
3	8	11222	WASHER FLAT 1.25 HARDENED
4	4	10023	NUT LOCK 1.12 UNF
5	4	CHART	PIVOT BUSHING

AL/TL/TA/CL AXLE SEAT MAINTENANCE HARDWARE KIT





AFFECTED	(EXCEPT AS NOTED)	SRK KIT					
7300		PREVIOUS ASSY: VAR	IES		W		
	FRACTIONAL ± 1/32	SUSPENSION MODEL: VARIES		1:16	WATSON & CHALIN		
	ANGULAR + 0.5 °	DATE: 10/23/06	DRAWN BY:	G	SIZE:	DRAWING NO: SRK02	

REPAIR KIT	NOTE:	ITEM #5	
SRK02	WITH BUSHING	11223	
SRK02-01	WITHOUT BUSHING	N/A	